

# 2018\_10 BMW Pre-scan Report

## Vehicle Information

2018\_10/BMW/X'/X1 sDrive20i\_B48/  
 VIN: WBAJG3A08K3H21006

Odometer Reading: 194111km  
 License Plate: 1234

## Customer Information

Name: --

Tel: --

## Device information

Scanner: MS906S  
 Version: V19.00

Serial Number: VS8GMBC01019  
 Repair Order Number: nasir2

## System Scanned( 19 )

System	Calibration	Status/DTC
DME (Engine-Digital Motor Electronics)		3
EGS (Electronic Transmission Management)		0
DSC (Dynamic Stability Control)		0
ACSM (Airbag-Advanced Crash Safety Module)		0
KOMBI (Instrument Cluster)		0
BDC (Body Domain Controller)		0
TRSVc (All Round View Camera)		0
ZGM (Central Gateway Module)		0
PMA (Parking Manoeuvring Assistant)		0
EPS (Electric Power Steering)		0
FLEL (Frontal Light Electronics Left)		0
FLER (Frontal Light Electronics Right)		0
FZD (Roof Function Center)		0
GWS (Gear Selector Switch)		0
TCB (Combox Emergency Call)		1
HUB (Headunit Basis)		1
CON (Controller)		0
SMFA (Driver Seat Module)		0

IHKA (Integrated Automatic Heating And A/C System)

 0 **Pre-scan DTC ( 5 )****DME (Engine-Digital Motor Electronics) ( 3 DTCs )**

DTC	Description	Status
118402	Mixture control: Mixture too rich, deviation too high	Intermittent
1F0549	Check Control message (ID 2064): Service requires engine oil!	Permanent
118002	Mixture control: Fuel-air mixture too rich	Intermittent

**TCB (Combox Emergency Call) ( 1 DTC )**

DTC	Description	Status
031785	TCB: Functional limitation of breakdown call	Permanent

**HUB (Headunit Basis) ( 1 DTC )**

DTC	Description	Status
B7F8C6	CID: Reduction in brightness due to excess temperature	Intermittent

**Pre-scan Technician Notes**

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.