

Benz Vehicle Diagnostic Report

Vehicle Information

-- / Benz / 177.145 - A 220 4MATIC /
VIN: WDD3G4FB8LW040570

Odometer Reading: 70068.3km
License Plate: --



Scan to download PDF

Customer Information

Name: mercedes

Device information

Scanner: MaxiSys MS906 Pro
Version: V5.91

Serial Number: VA5GR4C02411
Repair Order Number: VA5GR4C0241120241127052803760

System Scanned (39)

System	Status/DTC
ECM(Engine Control Unit)	1
TCM(Transmission Control Unit)	0
ESP(Electronically controlled vehicle stability braking system control unit)	0
SRS(Supplemental Restraint System Control Unit)	0
LIN:WSS-1(Weight Sensing Sensor Control Unit)	0
KI(Instrument Cluster)	0
TPM(Tire Pressure Monitor Control Unit)	0
SAM(Signal Acquisition Control Unit)	0
LIN:AISP(Interior mirror)	0
LIN:BSN(Battery Sensor)	0
LIN:DBE-1(Sunroof Control Unit)	0
LIN:FSW(Wiper Motor)	0
LIN:VCS(Rain/sunlight sensor)	0
EZS(Electronic Ignition Lock Control Unit)	0
LIN:HSM(Rear Switching Control Unit)	0
ES(Electric Power Steering)	0
KLA(Air Conditioner Control Unit)	1

PTCU(Drivetrain Control Unit)		✓	0
AWD(Four Wheel Drive)		✓	0
HU(Head Unit Control Unit)		✓	0
SW-SW-R(Right Headlamp Control Unit)	ADAS	✓	0
SW-SW-L(Left Headlamp Control Unit)	ADAS	✓	0
LRE(Steering Wheel Electronics)		✓	0
SGR(Radar sensors control unit)	ADAS	✓	0
DMFL(Left Front Door Control Unit)		✓	0
LIN:DMRL(Left Rear Door Control Unit)		✓	0
DMFR(Right Front Door Control Unit)		✓	0
LIN:DMRR(Right Rear Door Control Unit)		✓	0
TPAD(TPAD)		✓	0
ZAN(Center Display Control Unit)		✓	0
RFK-C(Reversing Camera)	ADAS	✓	0
PSD(Sunroof Control Unit)		✓	0
MRM(Steering Column Control Unit)		✓	0
IRS-HRA(Right Rear Outer Driving Assist Radar)	ADAS	✓	0
IRS-HLA(Left Rear Outer Driving Assist Radar)	ADAS	✓	0
FSCU(Fuel Pump Control Unit)		✓	0
ESEP(Passenger Side Electric Seat Adjustment Control Unit)		✓	0
ESED(Driver Side Electric Seat Adjustment Control Unit)		✓	0
DTA(Telematics Service Control Unit)		✓	0

 **DTC (2)**

ECM(Engine Control Unit) (1 DTC)

DTC	Description	Status
-----	-------------	--------

P13C500 A short-term torque limitation was detected by the knock control. Stored

KLA(Air Conditioner Control Unit) (1 DTC)

DTC	Description	Status
B112749	The air quality sensor has a malfunction. There is an internal electrical fault.	Active and stored

Technician Notes

Customer Name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.