

2021/02- Nissan Vehicle Diagnostic Report

Vehicle Information

2021/02- / Nissan / Qashqai/Rogue Sport /
VIN: JN1BJ1AW7MW668835

Odometer Reading: 58715km
License Plate: --



Scan to download PDF

Customer Information























Name: Farees

Device information

Scanner: MaxiSys MS906 Pro
Version: V6.50

Serial Number: VA5GR4C02411
Repair Order Number: VA5GR4C0241120241020034659242

System Scanned (21)

| System | Status/DTC |
|--------------------------------------|---|
| Engine |  0 |
| Transmission |  4 |
| ABS |  0 |
| Air bag |  1 |
| Meter/M&A |  0 |
| Electric Power Steering (EPS)/DAST 3 |  0 |
| Left rear side radar |   0 |
| Right rear side radar |   0 |
| Multi AV |  0 |
| Laser/radar |   0 |
| Lane camera |   0 |
| ICC/ADAS |   0 |
| HVAC |  0 |
| IPDM E/R |  0 |
| All mode AWD/4WD |  0 |
| Sonar |  0 |
| BCM |  0 |

| | | | |
|---|------|---|---|
| Chassis control | ADAS | ✓ | 0 |
| Intelligent Cruise Control (ICC)/Advanced Driver Assistance System (ADAS) 2 | ADAS | ✓ | 0 |
| 3-channel CAN gateway | | ✓ | 0 |
| Occupant detection | | ✓ | 0 |

DTC (5)

Transmission (4 DTCs)

| DTC | Description | Status |
|-------|-------------------------------|--------|
| P0705 | T/M range sensor A | Past |
| P0740 | Torque converter | Past |
| U0100 | Loss of communication (ECM) A | Past |
| U1000 | CAN COMM circuit | Past |

Air bag (1 DTC)

| DTC | Description | Status |
|----------|-------------------|---------|
| B0094:11 | Crash zone sensor | Current |

Technician Notes

Customer Name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.